## **SIEMENS**

Product data sheet 3RS1020-1DW00



TEMPERATURE MONITORING RELAY FOR PT100, EXCEEDING OF 2 THRESH. VAL., WIDTH 22ND5 MM -50 C-50 C, 110-120/220-240V AC 1 NO+1 W, LOAD + CL.-CIRC.CURR. SCREW CONNECTION

General technical details:				
type of voltage		AC/DC		
Supply voltage frequency				
• 1 / for auxiliary and control current circuit				
• initial rated value	Hz	50		
• final rated value	Hz	60		
• 1 / at 50 Hz / for AC / initial rated value	V	24		
• 1 / at 50 Hz / for AC / final rated value	V	240		
• 1 / at 60 Hz / for AC / initial rated value	V	24		
• 1 / at 60 Hz / for AC / final rated value	V	240		
• 1 / for DC / initial rated value	V	24		
• 1 / for DC / final rated value	V	240		
Number of measuring circuits		1		
Product function				
defect storage		No		
• reset external		No		
Measurable temperature				
• initial value	°C	-50		
• final value	°C	50		
Item designation / according to DIN EN 61346-2		К		

Item designation / according to DIN 40719 extendable after IEC 204-2 / according to IEC 750		К
Ambient temperature		
during operating	°C	-25 +60

Mechanical design:				
Design of the electrical connection				
for auxiliary and control current circuit		screw-type terminals		
• jumper socket		Yes		
Design of the sensor / connectable		PT100 (resistance sensor)		
Number of NC contacts / for auxiliary contacts		0		
Number of NO contacts / for auxiliary contacts		1		
Number of change-over switches / for auxiliary contacts		1		
Width	mm	22.5		
Height	mm	102		
Depth	mm	91		

## **Certificates/approvals:**

## **General Product Approval**







**Test Certificates** 

Special Test Certificate Declaration of Conformity

other

Environmental Confirmations

## **Further information:**

Information- and Downloadcenter (Catalogs, Brochures,...)

http://www.siemens.com/industrial-controls/catalogs

Industry Mall (Online ordering system)

http://www.siemens.com/industrial-controls/mall

Cax online generator:


http://www.siemens.com/cax


Service&Support (Manuals, Certificates, Characteristics, FAQs,...)

http://support.automation.siemens.com/WW/view/en/3RS1020-1DW00/all

Image database (product images, 2D dimension drawings, 3D models, device circuit diagrams, ...)

http://www.automation.siemens.com/bilddb/cax\_en.aspx?mlfb=3RS1020-1DW00





last change: Jan 25, 2013